# **Metallic Materials**

## **Phase Transformations in Metals**

### Why Study Phase Transformations in Metals?

- The development of a set of desirable mechanical properties for a material often results from a phase transformation, which is wrought by a heat treatment.
- The time and temperature dependencies of some phase transformations are conveniently represented on modified phase diagrams.

It is important to know how to use these diagrams in order to design a heat treatment for some alloy that will yield the desired room-temperature mechanical properties.

 The tensile strength of an iron-carbon alloy of eutectoid composition (0.76wt% C) can be varied between ~ 700 MPa and 2000 MPa depending on the heat treatment employed. How to tailor mechanical properties of metallic materials?

- Four strengthening mechanisms:
  - Grain size refinement
  - Solid-solution strengthening
  - Strain hardening
  - Precipitation hardening
- Additional techniques are available wherein the mechanical properties are reliant on the characteristics of the microstructure.
- The development of microstructure in both singleand two-phase alloys ordinarily involves some type of phase transformation — an alteration in the number and/or character of the phases.



The iron-iron carbide phase diagram



#### Important Phases in the Iron-Iron Carbide System

- Thermal processing or heat treating: the art and science of controlling thermal energy for the purpose of altering the properties of metals and alloys
  - Ferrite (α-Fe): Pure Fe (room temperature to 912°C), a single-phase BCC solid solution

Ferrite can accommodate 0.022% carbon at 727°C.

- Austenite ( $\gamma$ -Fe): a single-phase FCC solid solution  $\alpha$  ferrite transforms from BCC to FCC at 912°C.

Characteristics: ability to be deformed and to absorb carbon up to 2.14% at 1147°C

 Cementite (iron carbide Fe<sub>3</sub>C): intermediate phase with the chemical formula Fe<sub>3</sub>C

6.70% C: brittle and hard

# The Iron–Iron Carbide Phase Diagram.



### Important Phases in the Iron-Iron Carbide System (Cont'd)

#### - Pearlite:

When steel with the eutectoid composition forms at 727°C, it produces a lamellar twophase mixture of ferrite and cementite

- Hypoeutectoid steel: a mixture of ferrite and pearlite
- Hypereutectoid steel: a mixture of pearlite and cementite

#### **Pearlite Microstructure**



α ferrite (light phase)

Fe<sub>3</sub>C (dark phase)

Pearlite has mechanical properties between the soft, ductile ferrite and the hard, brittle cementite.

Photomicrograph of a eutectoid steel showing the pearlite microstructure consisting of alternating layers of  $\alpha$  ferrite (the light phase) and Fe<sub>3</sub>C (thin layers most of which appear dark). 500X.

## **The Iron-Iron Carbide System**

 One eutectic reaction exists for the iron-iron carbide system, at 4.30wt% C and 1147°C (Line PEG).

L (4.30wt% C)  $\rightarrow \gamma$  (2.14wt% C) + Fe<sub>3</sub>C (6.70wt% C)

 One eutectoid reaction exists for the iron-iron carbide system, at 0.76wt% C and 727°C (Line NOH).

 $\gamma$  (0.76wt% C)  $\rightarrow \alpha$  (0.022wt% C) + Fe<sub>3</sub>C (6.70wt% C)

### **Phase Transformations**

- Phase Transformation: a change in the number and/or character of the phases that constitute the microstructure of an alloy
- In general, two processes accompany the phase transformation such as the <u>eutectoid reaction</u>:
  - <u>Nucleation</u> the formation of very small particles, or nuclei, of the new phase

Favorable nucleation sites: imperfection sites, especially grain boundaries

- <u>Growth</u> — the increase of the nuclei in size

Some volume of the parent phase disappears.

# The Iron–Iron Carbide Phase Diagram.



## **The Limitation of Equilibrium Phase Diagrams**

- Unable to indicate the time period required for the attainment of equilibrium
- Equilibrium conditions are maintained only if heating or cooling is carried out at <u>extremely</u> <u>slow</u> and unpractical rates.

## Time-Temperature-Transformation (T-T-T) Diagrams

### **Pearlite**

 The eutectoid reaction is fundamental to the development of microstructures in steel alloys.

 $\gamma$  (0.76 wt% C)  $\rightleftharpoons \alpha$  (0.022 wt% C) + Fe<sub>3</sub>C (6.70 wt% C)

- Pearlite is the microstructural product of this transformation.
- Interpretation of the TTT diagram
  - Above eutectoid temperature: only <u>austenite</u> exists
  - Below eutectoid temperature: <u>nucleation</u> + <u>growth</u>
- The percentage of the transformation product is related to the holding <u>temperature</u> and holding <u>time</u>.



The iron–iron carbide phase diagram



The complete TTT diagram for an ironcarbon alloy of eutectoid composition. A: austenite B: bainite B: bainite M: martensite P: pearlite

## **TTT Diagram for a Eutectoid Fe-C Alloy**



Time (s)

### **Time-Temperature-Transformation (T-T-T) Diagrams**

#### **Pearlite**

- The thickness of the ferrite/cementite layers in pearlite depends on the temperature. With decreasing temperature, the layers become progressively thinner.
  - − At temperatures just below eutectoid → relatively thick layers → coarse pearlite
  - − In the vicinity of <u>540</u>°C → <u>relatively thin</u> layers → <u>fine</u> pearlite



- Smaller ∆T: colonies are larger



- Larger ∆T: colonies are smaller



Photomicrographs of (a) coarse pearlite and (b) fine pearlite. 3000X.



The complete isothermal transformation diagram for an ironcarbon alloy of eutectoid composition. A: austenite B: bainite B: bainite M: martensite P: pearlite

## Martensite

- Martensite is formed when <u>austenitized</u> Fe-C alloys are <u>rapidly</u> cooled (or <u>quenched</u>) to a relatively <u>low</u> temperature (in the vicinity of the ambient).
  - Non-equilibrium single phase
  - A transformation product that is competitive with pearlite
  - Transformation of FCC to BCT (body-centered tetragonal)
  - Occurs instantaneously  $\rightarrow$  <u>time-independent</u>
  - The martensite grains nucleate and grow at a very rapid rate — the velocity of sound within the austenite matrix.



The body-centered tetragonal unit cell for martensitic steel showing iron atoms (circles) and sites that may be occupied by carbon atoms (crosses). For this tetragonal unit cell, c > a.

![](_page_23_Picture_0.jpeg)

Lenticular or plate martensitic microstructure

Photomicrograph showing the lenticular or plate martensitic microstructure. The needle-shaped grains are the martensite phase, and the white regions are austenite that failed to transform during the rapid quench. 1220X.

![](_page_24_Figure_0.jpeg)

The complete isothermal transformation diagram for an ironcarbon alloy of eutectoid composition. A: austenite B: bainite B: bainite M: martensite P: pearlite

### **The Martensitic Transformation**

Since the martensitic transformation is instantaneous, it is not depicted in this diagram like the pearlitic reaction.

- The beginning of this transformation is represented by a horizontal line designated M(start).
- Two other horizontal and dashed lines, labeled M(50%) and M(90%), indicate percentages of the austenite-to-martensite transformation.
- The temperatures at which these lines are located vary with alloy composition; the temperatures must be relatively low.
- The horizontal and linear character of these lines indicates that the martensitic transformation is independent of time; it is a function only of the temperature to which the alloy is quenched.

![](_page_26_Figure_0.jpeg)

#### **Effects of alloying elements**

The presence of alloying elements other than carbon (e.g., Cr, Ni, Mo, and W) may cause significant changes in the <u>positions/shapes</u> of the curves in the isothermal transformation diagrams.

TTT diagram for an alloy steel (type 4340):

- A, austenite;
- B, bainite;
- P, pearlite;
- M, martensite;
- F, proeuctectoid ferrite.

![](_page_27_Figure_0.jpeg)

The complete isothermal transformation diagram for an ironcarbon alloy of eutectoid composition. A: austenite B: bainite B: bainite M: martensite P: pearlite

Using the isothermal transformation diagram for an iron-carbon alloy of eutectoid composition, specify the nature of the final microstructure of a small specimen that has been subjected to the <u>following time-</u> <u>temperature treatments</u>.

The specimen begins at 760°C and that it has been held at this temperature long enough to have achieved a <u>complete and homogeneous austenitic structure</u>.

(a) Rapidly cool to 250°C, hold for 100s, and quench to room temperature

(b) Rapidly cool to 600°C, hold for 10<sup>4</sup> s, and quench to room temperature

![](_page_29_Figure_0.jpeg)

(a) Rapidly cool to 250°C, hold for 100s, and quench to room temperature

(b) Rapidly cool to 600°C, hold for 10<sup>4</sup> s, and quench to room temperature

The time-temperature-transformation diagram for an ironcarbon alloy of eutectoid composition and the isothermal heat treatments

![](_page_30_Figure_0.jpeg)

- (a) Rapidly cool to 250°C, hold for 100s, and quench to room temperature
- At 760°C: in the austenite region (γ)— 100% austenite
- Rapidly cool from 760°C to 250°C: 100% austenite
- Hold for 100 seconds at 250°C: 100% austenite
- Quench to room temp.: 100% martensite

![](_page_31_Figure_0.jpeg)

- (b) Rapidly cool to 600°C, hold for 10<sup>4</sup> s, and cool to room temperature
- At 760°C: in the austenite region (γ)— 100% austenite
- Rapidly cool from 760°C to 600°C: 100% austenite
- Hold for 10<sup>4</sup> s at 250°C: 100% pearlite
- Quench to room temp.: 100% pearlite

## **Mechanical Behavior of Iron-Carbon Alloys**

#### **Pearlite**

- <u>Cementite</u> (Fe<sub>3</sub>C) is much harder but more brittle than <u>ferrite</u> ( $\alpha$ ).
- %  $Fe_3C \uparrow \Rightarrow strength\uparrow$ , ductility  $\downarrow$

#### **Martensite**

- Hardest and strongest, and most brittle
- Volume change  $\rightarrow \underline{crack}$  formation during quenching

### **Mechanical Properties of Fe-C Systems**

• Fine Pearlite vs Martensite:

![](_page_33_Figure_2.jpeg)

• Hardness: fine pearlite << martensite.